



Tel: 07732 103769

Email: dburak@hotmail.com

Address: 173A Neasham Road,  
Darlington DL1 4DF

# AMPED UP ELECTRICAL

## Quotation

Name: **Sillars properties**  
Address: **Tower house flat 4**  
Tel: .....

Date: **13/6/2022**

Job Description	Amount
Electric hob faulty, however 3 rings still work. Quote separately Hob only - replace hob	£285
In-line fan in bathroom broken and lights need replacing in kitchen fan Cost to replace these and install	£195
<b>Estimated Total</b>	<b>£480</b>



Any extra work carried out in addition to the above estimate will be charged separately.  
Estimate valid for 30 days from date produced.  
All prices exclude VAT and must be paid in full on day of completion.